

Devil's Gate Monitoring Log

Submitted By: SoCal_Bio

Submitted Time: 11/27/2018 3:45 PM

Project Name

Devil's Gate Reservoir Restoration Project - 2018-047.009

Date

Nov 19, 2018

Monitor Name

Carley Lancaster

Are Additional Monitors Present?

No

List Additional Monitors Present

N/A

Start Time

19:00

Start Temperature

49

Start Cloud Cover

20

Start Wind Speed

1-3

End Time

15:30

End Temperature

72

End Cloud Cover

10

End Wind Speed

1-3

Construction Activity and Personnel

Nature's Image crew used hand tools consisting of rakes and hoes to remove nonnative plant material. Crew consisted of 4 workers and two foreman (Haydee and Ron). All workers received training from Jerry Aguirre.

What type of monitoring is being conducted?

Restoration Monitoring

Was ESA swept prior to start of work?

Yes

Covered Species Observed?

No

Which Species were observed?

N/A

Were Any Non-compliance Issues Observed?

No

Please State What Non-compliance Issues Occurred:

N/A

Other Wildlife Species Observed

BNOW, BLPH ACWO CASJ, SCEOCC, SOSP, CALT, MODO, NOMO, YRWA, RTHA, TUVU, RCKI, BEWR

Topics to Cover on the Next Monitoring Day

Areas of focus, dumpster delivery, herbicide treatment.

Log Entry #1

0700, conducted pre-removal sweep of work area.

Log Entry #1 - Photos taken?

Yes

Log Entry #2

0745, crews began weed removal in southern portion of DG-4. All removed plant material was placed into garbage bags. Will be left onsite until dumpster arrival.

Log Entry #2 - Were Photos taken?

Yes

Log Entry #3

1530, final sweep of work area.

Log Entry #3 - Were Photos taken?

Yes

Log Completed?

Yes

Devil's Gate Monitoring Log

Submitted By: SoCal_Bio

Submitted Time: 12/04/2018 4:38 PM

Project Name

Devil's Gate Reservoir Restoration Project - 2018-047.009

Date

Nov 20, 2018

Monitor Name

Carley Lancaster

Are Additional Monitors Present?

No

List Additional Monitors Present

N/A

Start Time

07:00

Start Temperature

50

Start Cloud Cover

15

Start Wind Speed

1-3

End Time

15:30

End Temperature

7

End Cloud Cover

10

End Wind Speed

1-3

Construction Activity and Personnel

Nature's Image crew used hand tools to remove weedy plant material. Crew consisted of 4 workers and two foreman (Haydee Johnson and Ron Crawford).

What type of monitoring is being conducted?

Restoration Monitoring

Was ESA swept prior to start of work?

Yes

Covered Species Observed?

No

Which Species were observed?

N/A

Were Any Non-compliance Issues Observed?

No

Please State What Non-compliance Issues Occurred:

N/A

Other Wildlife Species Observed

BLPH, YRWA, BEWR, ACWO, CASJ, SCEOCC, RSHA, TUVU, AMCR, SOSP, WCSP, fox squirrel
Alligator lizard

Topics to Cover on the Next Monitoring Day

Dumpster bin delivery.

Log Entry #1

0700, conducted pre-removal sweep.

Log Entry #1 - Photos taken?

Yes

Log Entry #2

0715, weed removal, all removed material placed into trash bags (dumpster to be delivered tomorrow 11/21).

Log Entry #2 - Were Photos taken?

Yes

Log Entry #3

1530, conducted final sweep.

Log Entry #3 - Were Photos taken?

Yes

Log Completed?

Yes

Devil's Gate Monitoring Log

Submitted By: SoCal_Bio

Submitted Time: 12/07/2018 1:01 PM

Project Name

Devil's Gate Reservoir Restoration Project - 2018-047.009

Date

Nov 21, 2018

Monitor Name

Carley Lancaster

Are Additional Monitors Present?

No

List Additional Monitors Present

N/A

Start Time

07:00

Start Temperature

52

Start Cloud Cover

10

Start Wind Speed

1-3

End Time

15:00

End Temperature

71

End Cloud Cover

0

End Wind Speed

3-5

Construction Activity and Personnel

Nature's Image crew used hand tools to remove weedy plant material. Crew consisted of 16 workers and 3 foreman (Haydee Johnson, Ron Crawford, and Joe). WEAP training provided by Jerry Aguirre for new crew members.

What type of monitoring is being conducted?

Restoration Monitoring

Was ESA swept prior to start of work?

Yes

Covered Species Observed?

No

Which Species were observed?

N/A

Were Any Non-compliance Issues Observed?

No

Please State What Non-compliance Issues Occurred:

N/A

Other Wildlife Species Observed

ACWO, CASJ, RSHA, YRWA, CALT, BEWR, WEBL, SOSPO, SPTO, SCEOCC, cottontail AMCR, CAQU, NOMO, MODO

Topics to Cover on the Next Monitoring Day

Areas of focus. LEPLAT removal methods.

Log Entry #1

0700, conducted pre-removal sweep.

Log Entry #1 - Photos taken?

Yes

Log Entry #2

0745, weed removal, all removed plant material disposed of at onsite dumpster.

Log Entry #2 - Were Photos taken?

Yes

Log Entry #3

1500, conducted final sweep, crew done with removal will be conducting cleanup for the remainder of day.

Log Entry #3 - Were Photos taken?

Yes

Log Completed?

Yes

Devil's Gate Monitoring Log

Submitted By: SoCal_Bio

Submitted Time: 11/28/2018 2:39 PM

Project Name

Devil's Gate Reservoir Restoration Project - 2018-047.009

Date

Nov 26, 2018

Monitor Name

Carley Lancaster

Are Additional Monitors Present?

No

List Additional Monitors Present

N/A

Start Time

07:00

Start Temperature

50

Start Cloud Cover

15

Start Wind Speed

1-3

End Time

15:30

End Temperature

72

End Cloud Cover

10

End Wind Speed

1-3

Construction Activity and Personnel

Nature's Image crew used hand tools to remove weedy plant material. Crew consisted of 12 workers and three foreman (Haydee, Joe, and Ron). New crew members received WEAP training.

What type of monitoring is being conducted?

Restoration Monitoring

Was ESA swept prior to start of work?

Yes

Covered Species Observed?

No

Which Species were observed?

N/A

Were Any Non-compliance Issues Observed?

No

Please State What Non-compliance Issues Occurred:

N/A

Other Wildlife Species Observed

ACWO, CAQU, RTHA, YRWA, SOSP, NOMO, RCKI, CORA, AMKE

Topics to Cover on the Next Monitoring Day

Areas of focus. Missed areas.

Log Entry #1

0645, conducted pre-removal sweep.

Log Entry #1 - Photos taken?

Yes

Log Entry #1 Photo A



Log Entry #1 Photo B



Log Entry #2

0710, nonnative and weedy plant removal, all removed plant materials were disposed of in onsite dumpsters.

Log Entry #2 - Were Photos taken?

Yes

Log Entry #2 Photo A



Log Entry #2 Photo B



Log Entry #3

1530, crew done for the day, conducted final sweep.

Log Entry #3 - Were Photos taken?

Yes

Log Entry #3 Photo A



Survey Completed?

Yes

Signature

A handwritten signature in black ink, consisting of several loops and a long horizontal stroke extending to the right.

Devil's Gate Monitoring Log

Submitted By: SoCal_Bio

Submitted Time: 11/27/2018 3:44 PM

Project Name

Devil's Gate Reservoir Restoration Project - 2018-047.009

Date

Nov 27, 2018

Monitor Name

Carley Lancaster

Are Additional Monitors Present?

Yes

List Additional Monitors Present

Lauren Simpson

Start Time

07:00

Start Temperature

51

Start Cloud Cover

15

Start Wind Speed

0-3

End Time

15:00

End Temperature

70

End Cloud Cover

90

End Wind Speed

1-3

Construction Activity and Personnel

Nature's Image crew used hand tools consisting of rakes and hoes to remove nonnative plant material. Crew consisted of 14 workers and four foreman (Haydee, Isabella, Joe, and Ron). New workers received training from Lauren Simpson.

What type of monitoring is being conducted?

Restoration Monitoring

Was ESA swept prior to start of work?

Yes

Covered Species Observed?

No

Which Species were observed?

N/A

Were Any Non-compliance Issues Observed?

No

Please State What Non-compliance Issues Occurred:

N/A

Other Wildlife Species Observed

BEWR, YRWA ACWO, CASJ, SCEOCC, RCKI, MAKE, CORA, SOSP, MODO, RSHA

Topics to Cover on the Next Monitoring Day

Areas of focus. Cleaning up all removed material before end of day.

Log Entry #1

0645, conducted pre-removal sweep of work area.

Log Entry #1 - Photos taken?

Yes

Log Entry #2

0715, weed removal in DG-4. Plant material removed with hand tools and hauled to onsite dumpster.

Log Entry #2 - Were Photos taken?

Yes

Log Entry #3

0930, full dumpsters picked up by Republic Service.

Log Entry #3 - Were Photos taken?

No

Log Entry #4

1015, encounter with Sharon from local news station, briefly explained that crew was removing nonnative plant material for restoration purposes.

Log Entry #4 - Were Photos taken?

No

Log Entry #5

1205, empty dumpster delivered.

Log Entry #5 - Were Photos taken?

Yes

Log Entry #6

1300, crew tarping and hauling removed plant material to new dumpster.

Log Entry #6 - Were Photos taken?

Yes

Log Entry #7

1320, second empty dumpster delivered.

Log Entry #7 - Were Photos taken?

No

Log Entry #8

1530, crew done for day. Conducted final sweep of work area.

Log Entry #8 - Were Photos taken?

Yes

Log Completed?

Yes

Devil's Gate Monitoring Log

Submitted By: SoCal_Bio

Submitted Time: 11/27/2018 3:04 PM

Project Name

Devil's Gate Reservoir Restoration Project - 2018-047.009

Date

Nov 27, 2018

Monitor Name

Lauren Simpson

Are Additional Monitors Present?

Yes

List Additional Monitors Present

Carley Lancaster

Start Time

07:00

Start Temperature

56

Start Cloud Cover

10

Start Wind Speed

0-

End Time

15:02

End Temperature

73

End Cloud Cover

90

End Wind Speed

1-3

Construction Activity and Personnel

Nature's Image eucalyptus tree removal, crew of 3 using heavy machinery

What type of monitoring is being conducted?

Restoration Monitoring

Was ESA swept prior to start of work?

Yes

Covered Species Observed?

No

Which Species were observed?

N/A

Were Any Non-compliance Issues Observed?

No

Please State What Non-compliance Issues Occurred:

N/A

Other Wildlife Species Observed

BLPH, CALT, AMCR, ANHU, NUWO, RTHA, CASJ, MODO, YRWA, COHA, NOFL, RCKI

Topics to Cover on the Next Monitoring Day

Finish eucalyptus tree removal in eastern access road region.

Log Entry #1

Arrived onsite 0700. Gave WEAP training to 4 workers at 07450800 equipment arrived

Log Entry #1 - Photos taken?

No

Log Entry #2

0845 two eucalyptus removed on west side near access road using bat method. Inspected trees no bats observed

Log Entry #2 - Were Photos taken?

Yes

Log Entry #3

0900 guided crew to east side through north entrance 0930 confirmed with Griffith, LACDPW, and veg removal crew re: location to store fallen euks 0945 crew began removing euks from east access road area, bat method applied when appropriate sized tree was removed. Storing fallen trees in staging area after being cleared by biologist. Broke for lunch at 1100

Log Entry #3 - Were Photos taken?

Yes

Log Entry #4

Resumed work 1145. Continued removal of euk trees. Approximately 40 trees removed this day, appx 25 using bat method. No bats observed.

Log Entry #4 - Were Photos taken?

Yes

Log Completed?

Yes

Devil's Gate Monitoring Log

Submitted By: SoCal_Bio

Submitted Time: 11/28/2018 2:41 PM

Project Name

Devil's Gate Reservoir Restoration Project - 2018-047.009

Date

Nov 28, 2018

Monitor Name

Carley Lancaster

Are Additional Monitors Present?

Yes

List Additional Monitors Present

Adam Schroeder, Lauren Simpson, Torrey Rotellini

Start Time

07:00

Start Temperature

50

Start Cloud Cover

0

Start Wind Speed

1-3

End Time

15:00

End Temperature

65

End Cloud Cover

10

End Wind Speed

0-2

Construction Activity and Personnel

Nature's Image crew used hand tools to remove weedy or nonnative plant material. Crew consisted of 8 workers and two foreman (Ron and Joe).

What type of monitoring is being conducted?

Restoration Monitoring

Was ESA swept prior to start of work?

Yes

Covered Species Observed?

No

Which Species were observed?

N/A

Were Any Non-compliance Issues Observed?

No

Please State What Non-compliance Issues Occurred:

N/A

Other Wildlife Species Observed

Bobcat, COHA, YRWA, RCKI, CASJ, BEWR, SOSP, ACWO, RTHA, AMKE

Topics to Cover on the Next Monitoring Day

Areas of focus. Continuing to remove LEPLAT from base to remove root material.

Log Entry #1

0645, conducted pre-removal sweep.

Log Entry #1 - Photos taken?

Yes

Log Entry #2

0700, weed removal, all removed material was hauled to onsite dumpster.

Log Entry #2 - Were Photos taken?

Yes

Log Entry #3

0900, met with LACDPW, walked site and talked to crew.

Log Entry #3 - Were Photos taken?

No

Log Entry #4

1515, crew done removing plant material, conducted final sweep. Crew instructed to secure all dumpsters prior to leaving site.

Log Entry #4 - Were Photos taken?

Yes

Log Completed?

Yes

Devil's Gate Monitoring Log

Submitted By: SoCal_Bio

Submitted Time: 11/28/2018 2:40 PM

Project Name

Devil's Gate Reservoir Restoration Project - 2018-047.009

Date

Nov 28, 2018

Monitor Name

Adam Schroeder

Are Additional Monitors Present?

Yes

List Additional Monitors Present

Lauren Simpson, Carley Lancaster, Torrey Rotellini

Start Time

07:00

Start Temperature

3

Start Cloud Cover

0

Start Wind Speed

0-1

End Time

10:50

End Temperature

66

End Cloud Cover

5

End Wind Speed

0-2

Construction Activity and Personnel

Nature's image eucalyptus removal1. One Front Loader with mulching attachment2. Three Nature's Image Personnel

What type of monitoring is being conducted?

Restoration Monitoring

Was ESA swept prior to start of work?

Yes

Covered Species Observed?

No

Which Species were observed?

N/A

Were Any Non-compliance Issues Observed?

No

Please State What Non-compliance Issues Occurred:

N/A

Other Wildlife Species Observed

CORA, ANHU, MODO, BLPH, RTHA, WSCJ, NOMO, RCKL, YRWA

Topics to Cover on the Next Monitoring Day

None

Log Entry #1

0745, eucalyptus tree/bat habitat removal monitoring. No bats observed.

Log Entry #1 - Photos taken?

Yes

Log Entry #1 Photo A



Log Entry #1 Photo B



Log Entry #1 Photo C



Survey Completed?

Yes

Signature

Handwritten signature in black ink.

Devil's Gate Monitoring Log

Submitted By: SoCal_Bio

Submitted Time: 11/28/2018 4:35 PM

Project Name

Devil's Gate Reservoir Restoration Project - 2018-047.009

Date

Nov 28, 2018

Monitor Name

Lauren Simpson

Are Additional Monitors Present?

Yes

List Additional Monitors Present

Adam Schroeder, Carley Lancaste , Torrey Rotellini

Start Time

07:00

Start Temperature

49

Start Cloud Cover

0

Start Wind Speed

1-2

End Time

15:55

End Temperature

69

End Cloud Cover

90

End Wind Speed

1-3

Construction Activity and Personnel

Grubber, 2 bulldozers, 3 backhoes, 1 excavator Griffith crew & JV crew, about 25 crew members

What type of monitoring is being conducted?

Construction Monitoring

Was ESA swept prior to start of work?

Yes

Covered Species Observed?

No

Which Species were observed?

N/A

Were Any Non-compliance Issues Observed?

N/A

Please State What Non-compliance Issues Occurred:

N/A

Other Wildlife Species Observed

BLPH, ACWO, RTHA, CASJ, RCKI Western fence lizard, western toad, alligator lizard, wood rat, ALHU, cotton tail, side blotch lizard

Topics to Cover on the Next Monitoring Day

Access road veg removal outside reservoir

Log Entry #1

0700, arrived on site. Conducted workers education. Discussed work plan with contractor and county

Log Entry #1 - Photos taken?

No

Log Entry #2

0900, inspected felled trees from restoration crew for bats. No bats found. Examined boundaries of work area, continued discussing plan of action for protected trees and boundaries

Log Entry #2 - Were Photos taken?

No

Log Entry #3

1015, initiation of vegetation clearing. Spoke with operators about plan of action for stopping work if animals in imminent danger. Monitored excavator removing veg along project eastern boundary 11:30 lunch.

Log Entry #3 - Were Photos taken?

Yes

Log Entry #3 Photo A



Log Entry #3 Photo B



Log Entry #3 Photo C



Log Entry #4

1200 crew continued veg removal along eastern boundary. Animals relocated: western toad, alligator lizard, western fence lizard. No bio issues observed. Oak tree number 4 removed, oak tree 3 avoided. Lauren has more photos

Log Entry #4 - Were Photos taken?


Yes

Log Entry #5

1530 crew finished for day. Stopped work at northern boundary. Work area swept no bio issues observed.

Survey Completed?

Yes

SignatureA handwritten signature in black ink, consisting of stylized, cursive letters that appear to be 'LB' followed by a long horizontal line extending to the right.

Devil's Gate Monitoring Log

Submitted By: SoCal_Bio

Submitted Time: 11/28/2018 6:51 PM

Project Name

Devil's Gate Reservoir Restoration Project - 2018-047.009

Date

Nov 28, 2018

Monitor Name

Adam Schroeder

Are Additional Monitors Present?

Yes

List Additional Monitors Present

Carley Lancaster, Torrey Rotellini, Lauren Simpson

Start Time

09:30

Start Temperature

63

Start Cloud Cover

5

Start Wind Speed

0-2

End Time

15:40

End Temperature

66

End Cloud Cover

95

End Wind Speed

1-3

Construction Activity and Personnel

J.V. Land Clearing vegetation removal1. Two bulldozers, 1 water truck2. Two operators, 1 water truck driver, 4 Laborers

What type of monitoring is being conducted?

Construction Monitoring

Was ESA swept prior to start of work?

Yes

Covered Species Observed?

No

Which Species were observed?

N/A

Were Any Non-compliance Issues Observed?

No

Please State What Non-compliance Issues Occurred:

N/A

Other Wildlife Species Observed

CORA, ANHU, MODO, BLPH, RTHA, WSCJ, NOMO, RCKL, YRWA, Western fence lizard, southern alligator lizard, western toad, desert woodrat, California kingsnake, Pacific gopher snake, orange throated whiptail, side blotched lizard

Topics to Cover on the Next Monitoring Day

N/A

Log Entry #1

0930, Met with Griffith Company and JV Land Clearing to discuss plan for vegetation clearing.

Log Entry #1 - Photos taken?

No

Log Entry #2

1120, Monitoring J.V. Land Clearing Crew clearing vegetation. Rescued and relocated 1 western fence lizard, 1 alligator lizard, 2 western toads, 1 CA kingsnake, 1 Orange throated whiptail, and found 1 dead desert woodrat. One injured Pacific gopher snake was found and relocated.

Log Entry #2 - Were Photos taken?

Yes

Log Entry #2 Photo A



Log Entry #2 Photo B



Log Entry #2 Photo C



Survey Completed?

Yes

Signature

A handwritten signature in black ink, appearing to be "Bryce Adk". The signature is written in a cursive, flowing style.

Devil's Gate Monitoring Log

Submitted By: SoCal_Bio

Submitted Time: 11/30/2018 2:32 PM

Project Name

Devil's Gate Reservoir Restoration Project - 2018-047.009

Date

Nov 30, 2018

Monitor Name

Torrey Rotellini

Are Additional Monitors Present?

No

List Additional Monitors Present

N/A

Start Time

07:25

Start Temperature

49

Start Cloud Cover

10

Start Wind Speed

1-3

End Time

07:37

End Temperature

67

End Cloud Cover

20

End Wind Speed

1-3

Construction Activity and Personnel

Natures image restoration crew , about 25 people. Using hand tools, rakes.

What type of monitoring is being conducted?

Restoration Monitoring

Was ESA swept prior to start of work?

Yes

Covered Species Observed?

No

Which Species were observed?

N/A

Were Any Non-compliance Issues Observed?

No

Please State What Non-compliance Issues Occurred:

N/A

Other Wildlife Species Observed

ALWP, AMCO, CASJ, RCKI, RSHA

Topics to Cover on the Next Monitoring Day

Make sure new large trash bins come to replace full bins. Perhaps try and get natures image to get access to more bins.

Log Entry #1

0730. Conducted workers education program, met restoration crew. Discussed plan of action, conducted sweep of area to be cleared of nonnatives

Log Entry #1 - Photos taken?

No

Log Entry #2

1000, foreman (Ron) expressed concerns about not receiving a new trash bin for vegetation debris. New plan of action is to tarp up vegetation and bag it up near the trash bins for pick-up on Monday. Lunch at 11:00

Log Entry #2 - Were Photos taken?

Yes

Log Entry #2 Photo A



Log Entry #2 Photo B



Log Entry #2 Photo C



Log Entry #3

1200 returned to work, vegetation clearing continued. 1230, possible sighting of yellow rumped warbler by worker. Not seen by biologist.

Log Entry #3 - Were Photos taken?

No

Log Entry #4

1315, crew stopped vegetation clearing, no space left in trash bins so crew will spend rest of day putting debris in trash bags and leave them by the bins. Initiated final sweep through work area to make sure it was clean of debris piles.

Log Entry #4 - Were Photos taken?

Yes

Log Entry #4 Photo A



Log Entry #4 Photo B



Log Entry #4 Photo C



Log Entry #5

1412. Crew managed to fit all veg material in dumpster, no black bags needed. Crew finishing up for the day, gathering equipment. No more veg cleanup for day. Biologist left site at 1430.

Log Entry #5 - Were Photos taken?

Yes

Log Entry #5 Photo A



Survey Completed?

Yes

Signature

A handwritten signature in black ink, appearing to be "J. V. K." with a horizontal line extending from the end of the letters.

Devil's Gate Monitoring Log

Submitted By: SoCal_Bio

Submitted Time: 11/30/2018 1:44 PM

Project Name

Devil's Gate Reservoir Restoration Project - 2018-047.009

Date

Nov 30, 2018

Monitor Name

Lauren Simpson

Are Additional Monitors Present?

Yes

List Additional Monitors Present

Christine Tischer, Adam Schroeder

Start Time

06:45

Start Temperature

48

Start Cloud Cover

40

Start Wind Speed

0-3

End Time

13:45

End Temperature

64

End Cloud Cover

40

End Wind Speed

1-5

Construction Activity and Personnel

JV and Griffith Crew, one excavator, 4 personnel

What type of monitoring is being conducted?

Construction Monitoring

Was ESA swept prior to start of work?

Yes

Covered Species Observed?

No

Which Species were observed?

N/A

Were Any Non-compliance Issues Observed?

No

Please State What Non-compliance Issues Occurred:

N/A

Other Wildlife Species Observed

CALT, AMCR, BLPH, CASJ, YRWA, MODO, NUWO, EUST, striped racer, coastal whiptail, alligator lizard, western fence lizard, AMKE, ACWO, NOFL, CAKI, woodrat

Topics to Cover on the Next Monitoring Day

Requirement for Carley to be present for Oak trimming. Staking of protected zone for oak trees.

Log Entry #1

0650 arrived on site, discussed work plan for day with crew. Will be working on east and west access road areas. Adam monitoring oak removal on east side, Christine and I on west side0700 WEAP trained one additional crew member0845 crew setting up fencing around protected oaks

Log Entry #1 - Photos taken?

Yes

Log Entry #1 Photo A



Log Entry #2

0945 started veg removal of CSS along western access road impact areas
1000 WEAP trained one additional JV staff
1030 went with Joe (Griffith) to identify any oaks that will need to be trimmed. Will need certified arborist to trim. Veg removal continued until 1245 pm
Rescued and relocated: 2 alligator lizards, 2 fence lizards, 1 coastal whiptail, 1 striped racer, 1 woodrat. Point taken in collector for whiptail

Log Entry #2 - Were Photos taken?

Yes

Log Entry #2 Photo A



Log Entry #2 Photo B



Log Entry #2 Photo C



Log Entry #2 Photo D



Log Entry #3

1300 After veg removal was completed, went with Griffith to identify oaks requiring protective fencing. Discussed work plan and need for monitors on Monday.1345 left site


Log Entry #3 - Were Photos taken?

No

Survey Completed?

Yes

Signature

A handwritten signature in black ink, consisting of several loops and a trailing line, positioned below the 'Signature' label.

Devil's Gate Monitoring Log

Submitted By: SoCal_Bio

Submitted Time: 11/30/2018 12:48 PM

Project Name

Devil's Gate Reservoir Restoration Project - 2018-047.009

Date

Nov 30, 2018

Monitor Name

Adam Schroeder

Are Additional Monitors Present?

Yes

List Additional Monitors Present

Christine Tischer, Lauren Simpson, Torrey Rotellini

Start Time

07:00

Start Temperature

48

Start Cloud Cover

35

Start Wind Speed

0-2

End Time

13:30

End Temperature

64

End Cloud Cover

50

End Wind Speed

1-3

Construction Activity and Personnel

1. One excavator (350), one bulldozer, and hand tools
2. JV Land Clearing crew, two operators (Jeremy and Cary), and 3 laborers. Gave WEAP training to one new member of the crew

What type of monitoring is being conducted?

Construction Monitoring

Was ESA swept prior to start of work?

Yes

Covered Species Observed?

No

Which Species were observed?

N/A

Were Any Non-compliance Issues Observed?

No

Please State What Non-compliance Issues Occurred:

N/A

Other Wildlife Species Observed

ANHU, BLPH, RSHA, WSCJ, CORA

Topics to Cover on the Next Monitoring Day

N/A

Log Entry #1

0715, conducted clearance sweep of access road location on east side of the dam. No biological constraints observed.

Log Entry #1 - Photos taken?

No

Log Entry #2

0818, monitored vegetation clearing along south side of new access road on the east side of the dam. Oak trees removed included #s 23, 24, 25, 26, 27, 28, 29, and 30.

Log Entry #2 - Were Photos taken?

Yes

Log Entry #2 Photo A



Log Entry #2 Photo B



Log Entry #2 Photo C



Survey Completed?

Yes

Signature

A handwritten signature in black ink, appearing to be "Bryce Smith". The signature is written in a cursive, flowing style.

Devil's Gate Monitoring Log

Submitted By: SoCal_Bio

Submitted Time: 11/30/2018 11:20 AM

Project Name

Devil's Gate Reservoir Restoration Project - 2018-047.009

Date

Nov 30, 2018

Monitor Name

Christine Tischer

Are Additional Monitors Present?

Yes

List Additional Monitors Present

Adam Schroeder, Lauren Simpson, Torrey Rotellini

Start Time

07:00

Start Temperature

48

Start Cloud Cover

35

Start Wind Speed

0-2

End Time

10:53

End Temperature

57

End Cloud Cover

30

End Wind Speed

Construction Activity and Personnel

Staking limits and installing ESA fencing around oaks. Began clearing of upper west access road. 1 excavator and operator, 2 surveyors, 6-8 person ground crew.

What type of monitoring is being conducted?

Construction monitoring

Was ESA swept prior to start of work?

Yes

Covered Species Observed?

No

Which Species were observed?

N/A

Were Any Non-compliance Issues Observed?

N/A

Please State What Non-compliance Issues Occurred:

N/A

Other Wildlife Species Observed

BLPH, CALT, YRWA, BEWR, woodrat (middens), NUWO, WESJ, HOFI, whiptail, fence lizard, alligator lizard, OATI, ACWO, RCKI, MODO, fritillary

Topics to Cover on the Next Monitoring Day

N/A

Log Entry #1

07:20 Pre-clearance survey of west access road area. 1 oak along existing road will be protected in place. Coastal sage scrub and 1 acacia tree in upper area to be removed. Not working in lower portion due to recent rain. A few woodrat middens in lower area.

Log Entry #1 - Photos taken?

Yes

Log Entry #1 Photo A




Log Entry #2

9:10 Excavator arrived on site. ESA boundaries around oaks being staked. Surveyors delineating limits of clearing for access road. Began removing vegetation at 9:30.

Log Entry #2 - Were Photos taken?

Yes

Log Entry #2 Photo A



Log Entry #3

10:45 Relocated 3 immature fence lizards, 1 immature whiptail, and 1 alligator lizard. Lauren S. to complete monitoring since only 1 operator/excavator and limited amount of work to be done.

Log Entry #3 - Were Photos taken?

No

Survey Completed?

Yes

Signature

